CLASSIFICATION	CONFIDENTIAL/SECURITY	Y INFORMATION
STATEXAIR X FBIX	DISTRIBUTION	
ARMUX AEC X Navy EV X		

- 4. Q. Could the existing facilities of the yard be expanded?
  - A. Yes. Plans had already been drawn up in late 1939 to extend both drydocks about 200 feet. No widening was contemplated, and owing to the docks' proximity to each other probably would not be feasible anyway. The lengthening process could be accomplished fairly easily however.
- 5. Q. What were some of the defects you noted in Soviet warships repaired in the yard?
  - A. I understand there are six weight classes of Soviet submarines. They are 150 tons, 250 tons, 500 tons, 750 tons, 1000 tons and 1500 tons. During 1940, 150 ton, 250 ton, 750 ton and 1500 ton submarines were repaired at Liepaja. Although Latvians were permitted inside Nezi warships during the German occupation, the Soviets never permitted uLatvian inside of one of their craft, so most of our repairs were conducted on the exterior of some ships. When a Diesel engine needed changing, a special Soviet crew was brought in from the USSR to remove the engine from the ship under repair and transport it to the Diesel shop for repairs by Latvians under Soviet surveillance. External repairs consisted of re-welding sprung plates. On the smaller submarines, there was evidence of poor plate construction. Some of the submarines also suffered from chronic rudder trouble. and difficulty with the water ejection system which pumps the ballast tanks. There was some talk by Soviet crewmen of chlorination pollution of the submarine from the batteries, but their tones were not alarmist.
- 6. Q. Describe the condition of the shippard when you left 25X1
  - A. The shipperd was virtually undamaged by the evacuating Soviet and Nazi armies in the period 1940 to 1945. Although the Nazis planned to raze the yard prior to their retrest from the city in 1945, I understand from friends that they never had the chance owing to the rapid Soviet advance.
- 7. Q. Comment on any other installations of significance at the yard.
  - A. As you will note in the diagram /See Enclosure (A)/ there are adequate installations for all types of repairs. In addition, the yard acquired an 800 ton floating drydock in 1943, which apparently was not scuttled in 1945 as intended. The yard had one other floating drydock of 300 tons, also reported undamaged in 1945.
- 8. Q. What was the calibre of Soviet conduct and administration during the USSR occupation of 1940-1941?
  - A. Soviet administration was frantic and disorganized in 1940. Confusion, duplication of effort, and suspicion of sabotage were rampant throughout the Soviet visitation. Every failure or mistake was met with the Soviet charge of "fascist sabotage." The Soviet Commandant used the threat of imprisonment constantly until he realized that the exhausted Latvian workers under his rule had reached the point where they welcomed incarceration as an opportunity to escape Soviet authority.

Available for inspection and selection at the CIA Graphics Register is a 3" x 5" photograph of a Tosmares drydock.

ENCLOSURE (A): Mat with insert of Liepaja (to no scale) showing the location of Tosmares yard, and a close-up sketch (to no scale) of yard facilities.

CONFIDENTIAL/SECURITY INFORMATION

